



VEHICLE INSPECTION REPORT

RO64PNN

Audi Q3 2.0 TDI Quattro S Line Plus 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	25/10/2014	Body Style	Estate	Last service miles	94,235
Year	2014	Keys	2	MOT Due	08/11/2026
Mileage	99,172 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	8		
VIN	WAUZZZ8U3ER119430	Last service date	13/10/2025		

£90 ADDITIONAL FEE

last service 13/10/25 @ 94,235 miles (8 main dealer) Knocking noise while in park when in drive getting quiet

Tyres

NSF	COMFORSER	5.0mm
NSR	FALKEN	4.0mm
OSF	PIRELLI	3.0mm
OSR	FALKEN	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Chipped
1 To 5



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Door osr
Scratched
UpTo 25mm Thru Paint



13: Door osf
Dented
2 Or Less UpTo 10mm



14: Wing osf
Chipped
1 To 5



15: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK