



VEHICLE INSPECTION REPORT

KV69TNX

Mercedes-Benz B Class B220d AMG Line Premium Plus 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	06/12/2019	Body Style	MPV	Last service miles	85,577
Year	2019	Keys	2	MOT Due	05/12/2026
Mileage	96,366 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	BLUE	Number of stamps	6		
VIN	WDD2470142J090227	Last service date	03/07/2025		

£90 ADDITIONAL FEE
 last service 3/7/25 @ 85,577 miles (6 main dealer)

Tyres

NSF	LAUFENN	3.0mm
NSR	LAUFENN	5.0mm
OSF	LAUFENN	3.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Wheel osr
Corroded
Light



9: Wheel nsr
Corroded
Light



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Door nsr
Chipped
1 To 5



12: Door nsr
Dented
2 Or Less UpTo 10mm



13: Door nsf
Scratched
Over 25mm Thru Paint



14: Wheel nsf
Scratched
Over 50mm



15: Wing nsf
Scratched
UpTo 25mm Thru Paint



16: Bumper Front Moulding
Broken
Replace



17: Bumper Front
Chipped
Multiple Chips



18: Bonnet
Chipped
Multiple Chips



19: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		