



VEHICLE INSPECTION REPORT

LV67COJ

Nissan Qashqai 1.2 DiG-T Tekna 5dr Xtronic

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/09/2017	Body Style	Hatchback	Last service miles	30,959
Year	2017	Keys	2	MOT Due	10/05/2027
Mileage	65,377 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Printout	Gears	1
Colour	GREY	Number of stamps	1	Doors	5
VIN	SJNFEAJ11U2035515	Last service date	30/05/2022		

£90 ADDITIONAL FEE

Last service 30/05/2022 at 30,959 miles- 1 main dealer service

Tyres

NSF	BUDGET	3.0mm
NSR	ACCELERA	4.0mm
OSF	BUDGET	3.0mm
OSR	EVENT	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osr
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm



6: Bumper Rear
Poor Previous Repair
Paint Flake



7: Qtr Panel nsr
Dented
With Paint Damage



8: Door nsr
Dented
With Paint Damage



9: Wheel nsf
Scratched
Over 50mm



10: Door nsf
Chipped
Multiple Chips



11: Wheel nsf
Scratched
Over 50mm



12: Bonnet
Scratched
Over 25mm Thru Paint



13: Bumper Front
Scratched
UpTo 25mm Thru Paint



14: Wing nsf
Dented
2 Or Less UpTo 10mm



15: Door osr
Dented
Between 10mm + 30mm

16: Door osf
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		