



# VEHICLE INSPECTION REPORT

**GY70WPA**

## Nissan Qashqai 1.3 DiG-T 160 Tekna 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	24/10/2020	Body Style	Hatchback	Last service miles	26,796
Year	2020	Keys	2	MOT Due	22/02/2027
Mileage	53,045 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	BLACK	Number of stamps	3	Doors	5
VIN	SJNFFAJ11U2888573	Last service date	15/02/2023		

£90 ADDITIONAL FEE

Last service 15/02/2023 at 26,796 miles- 3 main dealer services

### Tyres




NSF	BUDGET	3.0mm
NSR	DUNLOP	4.0mm
OSF	DAVANTI	5.0mm
OSR	DUNLOP	4.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Radio/CD
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Dented  
With Paint Damage



6: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Up To 100mm



7: Door nsr  
Chipped  
1 To 5



8: Wheel nsr  
Scratched  
Over 50mm



9: Bumper Rear Moulding  
Scuffed (Unpainted)  
Over 100mm



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Wheel osr  
Scratched  
Over 50mm



13: Door osr  
Scratched  
Over 25mm Thru Paint



14: Door osf  
Chipped  
Edge Chip



15: Wing osf  
Chipped  
1 To 5



16: Wheel osf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK