



VEHICLE INSPECTION REPORT

ET68HNL

Volkswagen Golf 1.6 TDI SE [Nav] 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	21/01/2019	Body Style	Hatchback	MOT Due	15/04/2027
Year	2019	Service history	Yes	Gearbox	SEMI AUTO
Mileage	118,294 Miles Warranted	Service documents	Printout	Gears	6
Fuel Type	Diesel	Number of stamps	5	Doors	5
Colour	BLUE	Last service date	10/01/2025		
VIN	WVVZZZAUZKW065429	Last service miles	99,602		

LAST SERVICE 10/01/2025 @ 99,602 MILES (5 SERVICES, 4 MAIN DEALER)

Tyres

NSF	BUDGET	7.0mm
NSR	BUDGET	7.0mm
OSF	BUDGET	7.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Climate control
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Trip computer
- Heated door mirrors
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Alarm
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
Up To 25mm Thru Paint



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Qtr Panel nsr
Scratched
Up To 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Dented
Between 10mm + 30mm



10: Qtr Panel osr
Rusted
Over 5mm



11: Door osr
Scratched
Over 25mm Thru Paint



12: Door osf
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK