

# VEHICLE INSPECTION REPORT

**BG67RZB**

## Nissan Qashqai 1.6 DiG-T Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	29/09/2017	Body Style	Hatchback	Last service miles	16,583
Year	2017	Keys	2	MOT Due	28/09/2026
Mileage	37,000 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	1	Doors	5
VIN	SJNFCAJ11U2065490	Last service date	18/09/2019		

£90 ADDITIONAL FEE

LAST SERVICE 18/09/2019 @ 16,583 MILES (1 SERVICE, MAIN DEALER) Small engine knock when first started

### Tyres

NSF	AUTOGREEN	5.0mm
NSR	MAXXIS	5.0mm
OSF	AUTOGREEN	5.0mm
OSR	MAXXIS	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Poor Previous Repair  
Poor Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsf  
Dented  
Between 10mm + 30mm



5: Wheel nsr  
Scratched  
Over 50mm



6: A Post ns  
Dented  
Over 30mm



7: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



8: Wheel osr  
Scratched  
Up To 50mm



9: Door osf  
Chipped  
1 To 5



10: Wing osf  
Dented  
Over 30mm



11: Wheel osf  
Scratched  
Over 50mm

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK