



VEHICLE INSPECTION REPORT

RJ16KZV

Fiat 500 1.2 Lounge 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy

nama
GRADE
4

Details

Reg. date	31/05/2016	VIN	ZFA3120000J591208	Gearbox	MANUAL
Year	2016	Body Style	Hatchback	Gears	5
Mileage	57,114 Miles Warranted	Keys	2	Doors	3
Fuel Type	Petrol	Service history	None		
Colour	BLUE	MOT Due	12/11/2026		

COPY OF FRONT OF V5
 NO SERVICE HISTORY

Tyres

NSF	BUDGET	4.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	3.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- PAS
- Trip computer
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Alarm

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Dented
Over 30mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osf
Chipped
Edge Chip



12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Wheel osf
Scratched
Over 50mm



14: Seat Back Cover osr
Burn
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK