



VEHICLE INSPECTION REPORT

BJ65WFN

Vauxhall Corsa 1.4 SRi Vx-line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	12/10/2015	Body Style	Hatchback	Last service miles	87,030
Year	2015	Keys	2	MOT Due	13/10/2026
Mileage	102,815 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	9	Doors	5
VIN	W0L0XEP68G4026640	Last service date	17/10/2024		

£90 ADDITIONAL FEE

LAST SERVICE 17/10/2024 @ 87,030 MILES (9 SERVICES, 2 MAIN DEALER) Service tyre system message displayed

NSF wheel replaced by spare

Heath shield/ exhaust rattle

Tyres

NSF	SUNNY	5.0mm
NSR	LAUFENN	5.0mm
OSF	LAUFENN	5.0mm
OSR	LAUFENN	5.0mm
Spare		Punctured

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Drivers airbag
- Central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Full size spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Collision avoidance braking
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Poor Previous Repair
Poor Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Sill Panel Trim ns
Scratched (Painted)
UpTo 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Other
N/A
N/A



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Chipped
1 To 5



14: Door osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm




16: Door osf
Chipped
Edge Chip




17: Door osf
Chipped
1 To 5



18: Wing osf
Poor Previous Repair
Paint Flake



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Chipped
1 To 5



21: Tyre osf
 Damaged
 Replace

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK