



VEHICLE INSPECTION REPORT

HN22UWX

Vauxhall Crossland 1.2 Turbo [130] Ultimate 5dr Auto

| Inspection | | Vehicle | |
|-----------------|----|---------|--------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | TBC |

nama
GRADE
1

Details

| | | | | | |
|------------|---------------------------|--------------------|------------|-------------|------------|
| Reg. date | 23/04/2022 | Keys | 2 | CAP Average | £11,550.00 |
| Year | 2022 | Service history | Yes | CAP Below | £10,350.00 |
| Mileage | 17,177 Miles Warranted | Number of stamps | 2 | Gearbox | AUTOMATIC |
| Fuel Type | Petrol | Last service date | 24/04/2025 | Gears | 6 |
| Colour | ORANGE | Last service miles | 16,986 | Doors | 5 |
| VIN | W0V7H9EB9N4200211 | MOT Due | 22/04/2026 | | |
| Body Style | Hatchback | CAP Clean | £12,750.00 | | |

£65 ADDITIONAL FEE.

Tyres

| | | |
|-------|-------------|-------|
| NSF | BRIDGESTONE | 2.0mm |
| NSR | BRIDGESTONE | 3.0mm |
| OSF | BRIDGESTONE | 2.0mm |
| OSR | BUDGET | 4.0mm |
| Spare | | |

Features


- Bluetooth connection
- Rear parking sensor
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Auxiliary input socket
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Trip computer
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos






Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Wheel nsf
Scratched
Up To 50mm




4: Door nsf
Chipped
1 To 5



5: Door nsr
Scratched
Over 25mm Not Thru Paint



6: Bumper Rear
Scratched
Over 25mm Not Thru Paint



7: Boot Lid
Scratched
Over 25mm Not Thru Paint



8: Wheel osr
Scratched
Up To 50mm

No Image



9: Door osf
Scratched
Over 25mm Not Thru Paint

10: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |