



VEHICLE INSPECTION REPORT

BL16GXR

Ford Ecosport 1.0 EcoBoost Titanium 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/05/2016	Body Style	Hatchback	Last service miles	46,050
Year	2016	Keys	2	MOT Due	25/06/2026
Mileage	123,223 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	GREY	Number of stamps	1	Doors	5
VIN	WF0BXXMRKBGA69295	Last service date	28/10/2024		

£100 ADDITIONAL FEE
 LAST SERVICE 28/10/2024 @ 46,050 MILES (1 SERVICE)
 SOME MOTS ARE IN KM. Radio doesn't work

Tyres


NSF	ROADSTONE	5.0mm
NSR	BUDGET	5.0mm
OSF	LAUFENN	5.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- PAS
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Poor Previous Repair
Paint Flake



4: Door nsf
Chipped
Multiple Chips



5: Wheel nsr
Scratched
Over 50mm



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Qtr Panel osr
Dented
Between 10mm + 30mm



8: Door osr
Chipped
Edge Chip



9: Door osf
Chipped
Edge Chip



10: Wheel osf
Scratched
Over 50mm



11: Roof
Dented
Between 10mm + 30mm



12: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK