



# VEHICLE INSPECTION REPORT

**VN17XPA**

## Volkswagen Tiguan 2.0 TDi 150 4Motion SEL 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	25/05/2017	Body Style	Estate	Last service miles	89,983
Year	2017	Keys	2	MOT Due	03/06/2027
Mileage	97,202 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	7
Colour	GREY	Number of stamps	9		
VIN	WVGZZZ5NZHW429846	Last service date	29/05/2025		

£90 ADDITIONAL FEE

Last service 29/05/2025 at 89,983 miles- 9 services (4 main dealer) Book and print

### Tyres

NSF	RAPID	4.0mm
NSR	BUDGET	5.0mm
OSF	RAPID	4.0mm
OSR	BUDGET	5.0mm

### Spare

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front head restraints
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Alarm
- Cruise control
- PAS
- Trip computer
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Roof rails
- Front armrest
- Lumbar support
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Other  
N/A  
N/A



2: Bonnet  
Chipped  
1 To 5



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Dented  
Over 30mm



6: Door nsr  
Poor Previous Repair  
Poor Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Bumper Rear  
Scratched  
Up To 25mm Thru Paint




9: Tailgate  
 Scratched  
 UpTo 25mm Thru Paint



10: Door osr  
 Poor Previous Repair  
 Paint Flake



11: Door osf  
 Chipped  
 1 To 5



12: Screen Front  
 Cracked  
 Replace

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		