



VEHICLE INSPECTION REPORT

LT16EBX

Audi A6 Allroad 3.0 TDI [272] Quattro 5dr S Tronic

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	11/03/2016	Body Style	Estate	Last service miles	101,438
Year	2016	Keys	2	MOT Due	29/12/2026
Mileage	107,993 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	9		
VIN	WAUZZZ4G7FN074372	Last service date	10/10/2025		

£100 ADDITIONAL FEE

Last service 10/10/2025 at 101,438 miles- 9 services (2 main dealer) Timing belt noisy

Tyres



NSF	MAXXIS	4.0mm
NSR	MAXXIS	6.0mm
OSF	MAXXIS	4.0mm
OSR	MAXXIS	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Trip computer
- Heated door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Radio/CD
- Roof rails
- Front armrest
- Lumbar support
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear armrest
- Steering wheel reach adjustment
- Curtain airbags
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front head restraints
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Alarm

Photos





Condition Check



Damage Photos



1: Door osf
Scratched
Over 25mm Not Thru Paint



2: Door osf
Scratched
UpTo 25mm Thru Paint




3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Chipped
Multiple Chips



5: Wheel nsf
Scratched
Up To 50mm



6: Sill ns
Chipped
1 To 5



7: Wheel nsr
Scratched
Up To 50mm



8: Wheel osr
Scratched
Up To 50mm



9: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK