



VEHICLE INSPECTION REPORT

HN23VRT

Kia Picanto 1.0 2 5dr [4 seats]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy



Details

Reg. date	28/04/2023	Body Style	Hatchback	Last service miles	9,579
Year	2023	Keys	2	MOT Due	28/04/2027
Mileage	14,908 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	YELLOW	Number of stamps	2	Doors	5
VIN	KNAB3518LPT090385	Last service date	11/06/2025		

£100 ADDITIONAL FEE

Last service 11/06/2025 at 9579 miles- 2 main dealer services
PHOTOCOPY OF V5

Tyres


NSF	KUMHO	5.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	5.0mm
OSR		
Spare		

Features


- Bluetooth connection
- Media storage
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Dented
Between 10mm + 30mm



6: Door nsr
Chipped
1 To 5



7: Bumper Rear
Cracked
Over 25mm



8: Qtr Panel osr
Scratched
Up To 25mm Thru Paint



9: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



10: Door osf
Chipped
Edge Chip



11: Roof
Chipped
Edge Chip



12: Wing osf
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK