



# VEHICLE INSPECTION REPORT

**YC18GWK**

## BMW 2 Series 218d Sport 5dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	13/04/2018	Body Style	Estate	Last service miles	49,951
Year	2018	Keys	2	MOT Due	20/05/2027
Mileage	59,250 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	SILVER	Number of stamps	3		
VIN	WBA6W92000EC94688	Last service date	07/02/2025		

£90 ADDITIONAL FEE  
 LAST SERVICE 07/02/2025 @ 49,951 MILES (3 SERVICES)

### Tyres

NSF	BUDGET	6.0mm
NSR	APOLLO	6.0mm
OSF	APOLLO	3.0mm
OSR	APOLLO	6.0mm

Spare

## Features


- Bluetooth connection
- PAS
- Trip computer
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- Rear parking sensor
- Radio/CD
- Roof rails
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Alarm
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Dented  
With Paint Damage



3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsf  
Dented  
Over 30mm



5: Door nsr  
Scratched  
Over 25mm Thru Paint



6: Wheel nsr  
Scratched  
Over 50mm



7: Qtr Panel nsr  
Dented  
With Paint Damage



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint



9: Qtr Panel osr  
Dented  
With Paint Damage



10: Wheel osr  
Scratched  
Over 50mm



11: Door osr  
Dented  
With Paint Damage



12: Door osf  
Dented  
With Paint Damage



13: Wheel osf  
Scratched  
Over 50mm



14: Screen Front  
Chipped  
UpTo 10mm



15: B Post os  
Scratched  
Over 25mm Thru Paint

16: Roof  
Chipped  
Edge Chip

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK