



# VEHICLE INSPECTION REPORT

**GY70BXN**

## Peugeot 508 2.0 BlueHDi GT Line 5dr EAT8

nama  
 GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	21/09/2020	Body Style	Hatchback	Last service miles	10,281
Year	2020	Keys	2	MOT Due	15/10/2026
Mileage	11,378 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	RED	Number of stamps	5	Doors	5
VIN	VR3FHEHYRLY026499	Last service date	15/10/2025		

Last service 15/10/2025 at 10,281 miles- 5 main dealer services

### Tyres

NSF	MICHELIN	5.0mm
NSR	LAUFENN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	4.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Alarm
- Cruise control
- Park assist camera
- Trip computer
- Front fog lights
- Front armrest
- Lumbar support
- Steering wheel rake adjustment
- ABS
- Lane departure warning
- Remote central locking
- Front parking sensor
- PAS
- Radio/CD
- Air conditioning
- Front electric windows
- Rear armrest
- Steering wheel reach adjustment
- Blind spot information
- Passenger airbag
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front head restraints
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front Grill  
Broken  
Replace




3: Bumper Front  
Scratched  
25 to 100mm Thru Paint




4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Scratched  
Up To 25mm Thru Paint



6: Door nsf  
Chipped  
Edge Chip



7: Door nsr  
Chipped  
1 To 5



8: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



9: Qtr Panel osr  
Chipped  
1 To 5



10: Door osr  
Poor Previous Repair  
Poor Paint



11: Door osf  
Chipped  
Edge Chip



12: Wheel osf  
Scratched  
Over 50mm



13: Bumper Front Grill  
Broken  
Replace

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK