



VEHICLE INSPECTION REPORT

HF72WUC

Kia Xceed 1.5T GDi ISG 4 5dr

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	05/09/2022	Body Style	Hatchback	Last service miles	24,672
Year	2022	Keys	2	MOT Due	04/09/2026
Mileage	34,056 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	2	Doors	5
VIN	U5YH5F15LNL123993	Last service date	21/08/2025		

£90 ADDITIONAL FEE

LAST SERVICE 21/08/2025 @ 24,672 MILES (2 SERVICES, BOTH MAIN DEALER)

Tyres

NSF	NEXEN	2.0mm
NSR	CONTINENTAL	4.0mm
OSF	GT RADIAL	3.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Radio/CD
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Rear electric windows
- Metallic Paint
- Lane departure warning
- Alarm
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Telephone
- Electric door mirrors
- Air conditioning
- Front armrest
- Lumbar support
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Trip computer
- Front fog lights
- Climate control
- Front electric windows
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wing nsf
Chipped
1 To 5



4: Door nsr
Scratched
UpTo 25mm Thru Paint



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Door osf
Chipped
Edge Chip



7: Wheel nsf
Scratched
Over 50mm



8: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		