



VEHICLE INSPECTION REPORT

GV67RBF

Volkswagen Arteon 2.0 TSI R-Line 5dr DSG

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	12/02/2018	Body Style	Saloon	Last service miles	101,033
Year	2018	Keys	2	MOT Due	11/02/2027
Mileage	105,272 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	6	Doors	4
VIN	WVWZZZ3HZJE515080	Last service date	20/01/2026		

£90 ADDITIONAL FEE
 LAST SERVICE 20/01/2026 @ 101,033 MILES (6 SERVICES)

Tyres


NSF	PIRELLI	6.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	6.0mm
OSR	PIRELLI	6.0mm
Spare		

Photos






Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm



2: Wheel of
Scratched
Over 50mm



3: Bumper Front
Chipped
Over 5mm



4: Bonnet
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
Between 10mm + 30mm



9: Bumper Rear
Scratched
Up To 25mm Thru Paint



10: Qtr Panel osr
Dented
Over 30mm



11: Wheel osr
Scratched
Over 50mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK