



VEHICLE INSPECTION REPORT

RJ72ZGK

Mini Hatchback 1.5 Cooper Exclusive 3dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/12/2022	Body Style	Hatchback	Last service miles	58,173
Year	2022	Keys	2	MOT Due	27/12/2026
Mileage	59,607 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	BLUE/BLACK	Number of stamps	4	Doors	3
VIN	WMW32DH0302T94422	Last service date	01/05/2026		

£90 ADDITIONAL FEE

LAST SERVICE 01/05/2026 @ 58,173 MILES (4 SERVICES, ALL MAIN DEALER)

Tyres

NSF	BUDGET	6.0mm
NSR	PIRELLI	6.0mm
OSF	BUDGET	6.0mm
OSR	PIRELLI	6.0mm


Spare

Features


- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Service indicator
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel osr
Scratched
Up To 50mm



9: Qtr Panel osf
Scratched
UpTo 25mm Thru Paint



10: Door osf
Dented
Between 10mm + 30mm



11: Door osf
Chipped
Edge Chip



12: Wheel osf
Scratched
Over 50mm



13: Screen Front
Chipped
UpTo 10mm



14: Seat Back Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK