



VEHICLE INSPECTION REPORT

HV71WUA

Kia Xceed 1.0T GDi ISG Connect 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/10/2021	Body Style	Hatchback	Last service miles	29,896
Year	2021	Keys	2	MOT Due	28/10/2026
Mileage	35,000 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	ORANGE	Number of stamps	3	Doors	5
VIN	U5YH5F12LNL085658	Last service date	21/10/2025		

£90 ADDITIONAL FEE

LAST SERVICE 21/10/2025 @ 29,896 MILES (3 SERVICES, 2 MAIN DEALER) Pulley noisy

Tyres

NSF	BUDGET	5.0mm
NSR	KORMORAN	7.0mm
OSF	BUDGET	5.0mm
OSR	KORMORAN	7.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wing nsf
Chipped
1 To 5




4: Door nsf
Chipped
1 To 5



5: Door nsr
Scratched
Up To 25mm Thru Paint



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Qtr Panel osr
Chipped
1 To 5



9: Door osf
Dented
Over 30mm



10: Handle Outer osf
Scratched (Painted)
UpTo 25mm Thru Paint



11: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK