



VEHICLE INSPECTION REPORT

KM68XTA

Volkswagen Polo 1.0 TSI 115 SEL 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	19/12/2018	Body Style	Hatchback	MOT Due	12/09/2026
Year	2018	Service history	Yes	Gearbox	SEMI AUTO
Mileage	28,609 Miles Warranted	Service documents	Printout	Gears	7
Fuel Type	Petrol	Number of stamps	6	Doors	5
Colour	BLACK	Last service date	27/10/2025		
VIN	WVVZZZAWZKU010082	Last service miles	25,424		

£90 ADDITIONAL FEE

Last service 27/10/2025 at 25,424 miles- 6 main dealer services

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Reverse parking aid
- Trip computer
- USB/iPod interface
- Air conditioning
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Cloth seat trim
- Front parking sensor
- Service indicator
- Digital radio
- Body coloured bumpers
- Climate control
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Traction control
- Alloy wheels
- Rear parking sensor
- Steering wheel mounted controls
- Media storage
- Electric door mirrors
- Folding rear seats
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Tyre pressure monitor
- Rear wiper
- Telephone
- Mobile phone App interface
- LED headlights
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Remote central locking

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Wing osf
Chipped
1 To 5



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Bonnet
Chipped
1 To 5



5: Bumper Front
Scratched
UpTo 25mm Thru Paint



6: Bumper Front
Scratched
UpTo 25mm Thru Paint



7: Door nsr
Dented
Over 30% Of Panel



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Bumper Rear
 Scratched
 25 to 100mm Thru Paint



10: Bumper Rear
 Scratched
 25 to 100mm Thru Paint



11: Qtr Panel osr
 Scratched
 UpTo 25mm Thru Paint

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK