



VEHICLE INSPECTION REPORT

GU66XET

Mercedes-Benz B Class B200d AMG Line Premium Plus 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/09/2016	Body Style	MPV	Last service miles	44,160
Year	2016	Keys	2	MOT Due	10/10/2026
Mileage	75,290 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	SILVER	Number of stamps	4		
VIN	WDD2462082J416032	Last service date	11/10/2021		

£90 ADDITIONAL FEE

Last service 11/10/2021 at 44,160 miles- 4 main dealer services

Tyres

NSF	PACE	6.0mm
NSR	CONTINENTAL	5.0mm
OSF	PACE	6.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Seat Back Cover osf
Scuffed
Over 25mm



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Corroded
Light



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Tailgate
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel nsr
Dented
Over 30mm



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Door osf
Dented
Over 30mm



15: Wheel of
Scratched
Over 50mm



16: Wing of
Chipped
1 To 5



17: Screen Front
Chipped
Up To 10mm

Interior

Carpet Condition -
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		