



VEHICLE INSPECTION REPORT

RY19BUO

Kia Sportage 1.6T GDi ISG 4 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |



Details

| | | | | | |
|-----------|---------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 27/06/2019 | Body Style | Estate | Last service miles | 18,730 |
| Year | 2019 | Keys | 1 | MOT Due | 04/06/2027 |
| Mileage | 46,518 Miles Warranted | Service history | Yes | Gearbox | MANUAL |
| Fuel Type | Petrol | Service documents | Service Book | Gears | 6 |
| Colour | BLACK | Number of stamps | 1 | | |
| VIN | U5YPH816LKL652794 | Last service date | 30/04/2022 | | |

£90 ADDITIONAL FEE

Last service 30/04/2022 at 18,730 miles- 1 service. Book
Fuel flap not closing properly
Near side mirror camera faulty

Tyres



| | | |
|-------|---------|-------|
| NSF | HANKOOK | 2.0mm |
| NSR | HANKOOK | 5.0mm |
| OSF | HANKOOK | 2.0mm |
| OSR | HANKOOK | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: B Post os
Dented
2 Or Less UpTo 10mm



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Dented
Over 30% Of Panel



15: Door osf
Scratched
Over 25mm Thru Paint



16: Wing osf
Scratched
UpTo 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Bumper Front
Insecure
Action Required

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|----------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |

| | | | |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |