



# VEHICLE INSPECTION REPORT

**WG66KVT**

## HYUNDAI TUCSON 1.6 GDi Blue Drive SE 5dr 2WD

Inspection	Vehicle	
	VAT	Margin
	V5	Present

### Details

<b>Reg. date</b>	19/12/2016	<b>VIN</b>	TMAJ3811LHJ289005	<b>Last service date</b>	14/06/2024
<b>Year</b>	2016	<b>Body Style</b>	Estate	<b>Last service miles</b>	38,822
<b>Mileage</b>	54,190 Miles Warranted	<b>Service history</b>	Yes	<b>MOT Due</b>	19/05/2027
<b>Fuel Type</b>	Petrol	<b>Service documents</b>	Service Book	<b>Gearbox</b>	MANUAL
<b>Colour</b>	SILVER	<b>Number of stamps</b>	5	<b>Gears</b>	6

Last Service - 14.06.2024 at 38822 miles (5 services)

### Tyres

<b>NSF</b>	
<b>NSR</b>	
<b>OSF</b>	
<b>OSR</b>	
<b>Spare</b>	