

VEHICLE INSPECTION REPORT

GU60YED

Volkswagen FOX 1.2 Urban Fox 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	29/09/2010	VIN	WVWZZZ5ZZA4155824	Gearbox	MANUAL
Year	2010	Body Style	Hatchback	Gears	5
Mileage	154,040 Miles Warranted	Keys	2	Doors	3
Fuel Type	Petrol	Service history	None		
Colour	RED	MOT Due	29/08/2026		

£90 ADDITIONAL FEE

No service history Power steering faulty

Tyres

NSF	BUDGET	5.0mm
NSR	HANKOOK	5.0mm
OSF	BUDGET	5.0mm
OSR	TRIANGLE	5.0mm
Spare		

Features


- PAS
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Central locking
- Rear wiper
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Radio/CD
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



5: A Post ns
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Qtr Panel nsr
Dented
With Paint Damage



8: Bumper Rear
Scratched
Over 100mm Thru Paint




9: Qtr Panel osr
Scratched
Over 25mm Thru Paint




10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Door osf
Scratched
Over 25mm Thru Paint



12: Door osf
Dented
Between 10mm + 30mm



13: Wing osf
Dented
Over 30mm



14: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



15: Roof
Chipped
Multiple Chips

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	Fault