

# VEHICLE INSPECTION REPORT

**YF10ZWR**

## Vauxhall Astra 1.7 CDTi 16V ecoFLEX Exclusiv 5dr

nama  
GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	24/06/2010	Body Style	Hatchback	Last service miles	80,235
Year	2010	Keys	2	MOT Due	20/05/2027
Mileage	167,893 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	8	Doors	5
VIN	W0LPD6EG1A8081751	Last service date	15/10/2018		

Last service 15/10/2018 at 80,235 miles- 8 services (6 main dealer)


### Tyres



NSF	TRIANGLE	3.0mm
NSR	BUDGET	5.0mm
OSF	NEXEN	3.0mm
OSR	NEXEN	5.0mm
Spare		

### Features


- PAS
- Trip computer
- Climate control
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Radio/CD
- Folding rear seats
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Steel wheels
- Steering wheel mounted controls
- Air conditioning
- Steering wheel rake adjustment
- ABS
- Alarm

### Photos





## Condition Check



## Damage Photos



1: Roof Lining  
Scuffed  
Over 25mm



2: A Post os  
Poor Previous Repair  
Paint Flake



3: Wing osf  
Chipped  
Multiple Chips



4: Bumper Front  
Poor Previous Repair  
Poor Paint



5: Bonnet  
Scratched  
Over 25mm Thru Paint



6: Wing nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door nsr  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



10: Bumper Rear  
Poor Previous Repair  
Paint Flake



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Door osr  
Scratched  
Over 25mm Thru Paint



13: Door osf  
Scratched  
Over 25mm Thru Paint



14: Other  
N/A  
N/A



15: Screen Front  
Chipped  
Over 10mm

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK