



VEHICLE INSPECTION REPORT

HY13MUW

Vauxhall Corsa 1.2 ecoFLEX SXi 5dr [AC] [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	10/04/2013	Body Style	Hatchback	Last service miles	75,105
Year	2013	Keys	2	MOT Due	31/08/2026
Mileage	76,576 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	ORANGE	Number of stamps	10	Doors	5
VIN	W0L0SDL68D4135284	Last service date	11/08/2025		

last service 11/8/25 @ 75,105 miles (10 services 5 main dealer) book & print

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Alloy wheels
- Trip computer
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Alarm

Photos





Condition Check




Damage Photos



1: Wing of
Poor Previous Repair
Poor Colour




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



10: Door osr
Scratched
Over 25mm Thru Paint



11: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK