



# VEHICLE INSPECTION REPORT

**GR19NVY**

## SUZUKI CELERIO 1.0 SZ2 5dr

Inspection	Vehicle	
	VAT	Margin
	V5	Present

### Details

<b>Reg. date</b>	29/08/2019	<b>Body Style</b>	Hatchback	<b>MOT Due</b>	28/08/2026
<b>Year</b>	2019	<b>Service history</b>	Yes	<b>Gearbox</b>	MANUAL
<b>Mileage</b>	63,366 Miles Warranted	<b>Service documents</b>	Printout	<b>Gears</b>	5
<b>Fuel Type</b>	Petrol	<b>Number of stamps</b>	6	<b>Doors</b>	5
<b>Colour</b>	BLUE	<b>Last service date</b>	06/08/2025		
<b>VIN</b>	MMSLFE62S00118486	<b>Last service miles</b>	54,796		

LAST SERVICE 06/08/2025 @ 54,796 MILES (6 SERVICES, 1 MAIN DEALER)

### Tyres

NSF
NSR
OSF
OSR
Spare