

VEHICLE INSPECTION REPORT

XX55UZE

BMW 1 Series 120d Sport 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/12/2009	VIN	WBAUR32020VL25559	Last service date	23/07/2025
Year	2009	Body Style	Coupe	Last service miles	101,628
Mileage	103,950 Miles Warranted	Service history	Yes	MOT Due	03/08/2026
Fuel Type	Diesel	Service documents	Service Book	Gearbox	MANUAL
Colour	GREY	Number of stamps	11	Gears	6

Last Service - 23.07.2025 at 101628 miles (11 services)


Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	2.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Climate control
- Steering wheel rake adjustment
- Curtain airbags
- Tyre pressure monitor
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Alarm
- Trip computer
- Front fog lights
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Up To 25mm Thru Paint



2: Wheel of
Scratched
Up To 50mm



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Bonnet
Chipped
Multiple Chips



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
Multiple Chips



7: Other
N/A
N/A



8: Qtr Panel nsr
Chipped
Multiple Chips



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Reflector nsr
Broken
Replace



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Dented
Over 30mm



14: Wheel osr
Scratched
Over 50mm



15: Door osf
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK