



VEHICLE INSPECTION REPORT

BX13WJJ

BMW 1 SERIES 116i M Sport 5dr

Cat: S
 Inspection

Vehicle	
VAT	Margin
V5	Present

Details

Reg. date	03/03/2013	Body Style	Hatchback	MOT Due	15/01/2027
Year	2013	Service history	Yes	Gearbox	MANUAL
Mileage	99,747 Miles Warranted	Service documents	Printout	Gears	6
Fuel Type	Petrol	Number of stamps	2	Doors	5
Colour	BLUE	Last service date	13/02/2024		
VIN	WBA1A12070E693329	Last service miles	87,722		

£100 ADDITIONAL FEE

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair
 Last service 13/02/2024 at 87,722 miles- 2 services
 Timing chain replaced 24/06/2025 at 95,967 miles

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	