



VEHICLE INSPECTION REPORT

HN16VSM

Skoda Fabia 1.2 TSI 90 SE 5dr

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	13/05/2016	Body Style	Hatchback	Last service miles	32,324
Year	2016	Keys	2	MOT Due	12/07/2026
Mileage	65,395 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLUE	Number of stamps	1	Doors	5
VIN	TMBFM6NJ7GZ162359	Last service date	02/11/2020		

£90 ADDITIONAL FEE

Last service 02/11/2020 at 32,324 miles- 1 main dealer service

Tyres

NSF	FALKEN	5.0mm
NSR	FULDA	5.0mm
OSF	BUDGET	5.0mm
OSR	DUNLOP	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsf
Scuffed
Over 25mm



2: Carpets Front
Holed
Over 3mm



3: Other
N/A
N/A



4: Wheel osf
Scratched
Over 50mm



5: Wing osf
Chipped
1 To 5



6: Door osf
Chipped
Multiple Chips



7: Door osr
Scratched
Over 25mm Thru Paint



8: Qtr Panel osr
Chipped
Multiple Chips



9: Bumper Rear
Dented
With Paint Damage



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Qtr Panel nsr
Chipped
1 To 5



13: Wheel nsr
Scratched
Over 50mm



14: Door nsr
Chipped
1 To 5



15: Door nsf
Chipped
1 To 5




16: Door nsf
Scratched
UpTo 25mm Thru Paint



17: Wing nsf
Dented
With Paint Damage




18: Wheel nsf
Scratched
Over 50mm



19: Bumper Front
Scratched
Over 100mm Thru Paint



20: Bonnet
Scratched
Over 25mm Thru Paint



21: Roof
 Poor Previous Repair
 Paint Flake

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK