



# VEHICLE INSPECTION REPORT

**WR17XVJ**

## Toyota C-Hr 1.2T Excel 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |

nama  
GRADE  
**4**

### Details

|           |                           |                   |              |                    |            |
|-----------|---------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 16/05/2017                | Body Style        | Hatchback    | Last service miles | 72,390     |
| Year      | 2017                      | Keys              | 2            | MOT Due            | 17/04/2027 |
| Mileage   | 91,929 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL     |
| Fuel Type | Petrol                    | Service documents | Service Book | Gears              | 6          |
| Colour    | GREY                      | Number of stamps  | 3            | Doors              | 5          |
| VIN       | NMTKY3BX70R015149         | Last service date | 17/04/2024   |                    |            |

Last Service - 17.04.2024 at 72390 miles (3 services)

### Tyres

|       |          |         |
|-------|----------|---------|
| NSF   | FALKEN   | 4.0mm   |
| NSR   | MICHELIN | Damaged |
| OSF   | FALKEN   | 5.0mm   |
| OSR   | MICHELIN | 4.0mm   |
| Spare |          |         |

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Dented  
With Paint Damage



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Wheel osr  
Scratched  
Over 50mm



10: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



11: Qtr Panel osr  
Chipped  
1 To 5



12: Door osr  
Scratched  
UpTo 25mm Thru Paint



13: Door osf  
Scratched  
Over 25mm Thru Paint



14: Wheel osf  
Scratched  
Over 50mm



15: Wing Front Arch Extension os  
Scuffed (Unpainted)  
Over 100mm



16: Screen Front  
Chipped  
UpTo 10mm



17: Tyre nsr  
Damaged  
Replace

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                |    |  |    |
|----------------|----|--|----|
| Engine Runs    | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes         | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake  | OK | No Excessive Smoking                           | OK |

|                          |    |                                     |    |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated    | OK | Oil warning light illuminated       | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated    | OK |                                     |    |
| Windows                  | OK | Radio                               | OK |
| Sat nav                  | OK | Steering                            | OK |