



VEHICLE INSPECTION REPORT

YR14PXT

Renault Twingo 1.2 16V Dynamique 3dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	25/04/2014	Body Style	Hatchback	Last service miles	57,321
Year	2014	Keys	2	MOT Due	14/08/2026
Mileage	66,898 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	3	Doors	3
VIN	VF1CNJ60550747589	Last service date	07/05/2021		

Last service 07/05/2021 at 57,321 miles- 3 services Engine noisy tapping sound
 Broken air pipe

Tyres

NSF	FALKEN	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Cruise control
- Radio/CD
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- PAS
- Body coloured bumpers
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bonnet
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
Rusted



5: Qtr Panel nsr
Dented
Between 10mm + 30mm



6: Wheel nsr
Scratched
Over 50mm



7: Tailgate
Dented
Between 10mm + 30mm



8: Bumper Rear
Dented
With Paint Damage



9: Wheel osr
Scratched
Over 50mm



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Door osf
Poor Previous Repair
Rippled UpTo 30%



12: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK