



# VEHICLE INSPECTION REPORT

**DM63DEB**

## Vauxhall Adam 1.2i Glam 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	13/02/2014	Body Style	Hatchback	Last service miles	40,936
Year	2014	Keys	2	MOT Due	04/04/2027
Mileage	41,213 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	7	Doors	3
VIN	W0L0MAP08E6037348	Last service date	09/04/2026		

Last Service - 09.04.2026 at 40936 miles (7 services)

### Tyres


NSF	BUDGET	6.0mm
NSR	ANTARES	4.0mm
OSF	BUDGET	6.0mm
OSR	ANTARES	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Steering wheel rake adjustment
- Drivers airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Steering wheel reach adjustment
- Passenger airbag
- Cloth seat trim
- PAS
- Trip computer
- Air conditioning
- Front head restraints
- Metallic Paint
- Side airbags
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- ABS
- Alarm

## Photos





## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Bumper Front  
Poor Previous Repair  
Paint Flake



4: Bonnet  
Dented  
With Paint Damage



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



7: Bumper Rear  
Poor Previous Repair  
Paint Flake



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint



9: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



10: Door osf  
Dented  
Over 30mm



11: Door osf  
Scratched  
UpTo 25mm Thru Paint

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK