



VEHICLE INSPECTION REPORT

GV62KNU

Nissan X-Trail 2.0 dCi N-Tec+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	31/01/2013	Body Style	Estate	Last service miles	112,860
Year	2013	Keys	2	MOT Due	30/01/2027
Mileage	115,480 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	11		
VIN	JN1TCNT31U0404019	Last service date	23/01/2026		

Last service 23/01/2026 at 112,860 miles- 11 services (3 main dealer) Radio coded unable to check all features

Tyres



NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	EVENT	4.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Electric sunroof
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Fogdriving Lamp osf
Broken
Replace



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door Moulding nsf
Broken
Replace



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Chipped
1 To 5



11: Wheel nsr
Scratched
Up To 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Door nsr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



17: Door osf
Scratched
Over 25mm Thru Paint




18: Wheel osf
Scratched
Up To 50mm



19: Wing osf
Chipped
1 To 5



20: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



21: Screen Front
Chipped
UpTo 10mm



22: Sill os
Scratched
Rusted



23: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	Fault
Windows	OK	Steering	OK