



# VEHICLE INSPECTION REPORT

**LV62DFK**

## Nissan Qashqai 1.6 [117] N-Tec+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	21/09/2012	Body Style	Hatchback	Last service miles	91,938
Year	2012	Keys	1	MOT Due	30/07/2026
Mileage	107,273 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	10	Doors	5
VIN	SJNFAAJ10U2620590	Last service date	11/10/2023		

£100 ADDITIONAL FEE

Last service 11/10/2023 at 91,938 miles- 10 services (7 main dealer)

### Tyres


NSF	RAPID	2.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	Damaged
Spare		

### Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Cruise control
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Central locking
- Navigation system
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim

### Photos





## Condition Check



## Damage Photos



1: Wheel of  
Corroded  
Light



2: Wing of  
Scratched  
Up To 25mm Thru Paint



3: Door osr  
Scratched  
UpTo 25mm Thru Paint



4: Qtr Panel osr  
Poor Previous Repair  
Paint Flake



5: Wheel osr  
Corroded  
Light



6: Bumper Rear  
Poor Previous Repair  
Poor Paint



7: Tailgate  
Dented  
Over 30mm



8: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



9: Wheel nsr  
Corroded  
Light



10: Door nsr  
Dented  
With Paint Damage



11: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



12: Wheel nsf  
Corroded  
Light



13: Bonnet  
Chipped  
1 To 5



14: Other  
N/A  
N/A



15: Seat Base Cover osf  
Torn  
Over 3mm



16: Seat Back Cover osf  
Torn  
Over 3mm



17: Tyre osr  
Damaged  
Replace



18: Wing osf  
Dented  
2 Or Less UpTo 10mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Poor

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		