



VEHICLE INSPECTION REPORT

GC15DLJ

Peugeot 2008 1.2 PureTech Allure 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/07/2015	Colour	GREY	MOT Due	14/04/2027
Year	2015	VIN	VF3CUHMZ6FY089763	Gearbox	MANUAL
Mileage	82,401 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	Petrol	Service history	None	Doors	5

£100 ADDITIONAL FEE
 No service history

Tyres



NSF	TRIANGLE	4.0mm
NSR	RAPID	5.0mm
OSF	TRIANGLE	4.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- PAS
- Trip computer
- Front fog lights
- Folding rear seats
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Partial leather seat trim
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alarm

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Chipped
1 To 5



5: Screen Front
Chipped
UpTo 10mm



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel osr
Hole
Over 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK