



# VEHICLE INSPECTION REPORT

**WG66WJV**

## Renault Twingo 0.9 TCE Dynamique S 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	15/02/2017	Body Style	Hatchback	MOT Due	17/09/2026
Year	2017	Service history	Yes	Gearbox	MANUAL
Mileage	69,079 Miles Warranted	Service documents	Electronic / Online	Gears	5
Fuel Type	Petrol	Number of stamps	1	Doors	5
Colour	BLACK	Last service date	13/02/2023		
VIN	VF1AHB22556288774	Last service miles	44,681		

Last Service - 13.02.2023 at 44681 miles (1 CONFIRMED services at KCS Autos Wellington)

### Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	2.0mm
Spare		

### Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Climate control
- Rear headrests
- Drivers airbag
- Partial leather seat trim
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- Passenger airbag
- Alloy wheels
- PAS
- Trip computer
- Front fog lights
- Front head restraints
- Metallic Paint
- Alarm

### Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Chipped  
1 To 5



3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Bonnet  
Chipped  
Multiple Chips



5: Bonnet  
Scratched  
Over 25mm Thru Paint



6: Wheel nsf  
Scratched  
Over 50mm



7: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



8: Door nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Scratched  
Over 25mm Thru Paint



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Wheel osr  
Scratched  
Over 50mm



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Door osr  
Scratched  
Over 25mm Thru Paint



15: Door osf  
Chipped  
Edge Chip

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK