



# VEHICLE INSPECTION REPORT

**RA18RXX**

## KIA SPORTAGE 1.7 CRDi ISG 3 5dr

Inspection	Vehicle	
	VAT	Margin
	V5	Present

### Details

<b>Reg. date</b>	24/08/2018	<b>VIN</b>	U5YPH815LJL501139	<b>Last service date</b>	11/08/2025
<b>Year</b>	2018	<b>Body Style</b>	Estate	<b>Last service miles</b>	46,222
<b>Mileage</b>	50,350 Miles Warranted	<b>Service history</b>	Yes	<b>MOT Due</b>	23/08/2026
<b>Fuel Type</b>	Diesel	<b>Service documents</b>	Service Book	<b>Gearbox</b>	MANUAL
<b>Colour</b>	BLUE	<b>Number of stamps</b>	7	<b>Gears</b>	6

Last Service - 11.08.2025 at 46222 miles (7 services)

### Tyres

<b>NSF</b>	
<b>NSR</b>	
<b>OSF</b>	
<b>OSR</b>	
<b>Spare</b>	