



# VEHICLE INSPECTION REPORT

**RK16NYA**

## HYUNDAI TUCSON 1.7 CRDi Blue Drive SE Nav 5dr 2WD

| Inspection | Vehicle |        |
|------------|---------|--------|
|            | VAT     | Margin |
|            | V5      | TBC    |

### Details

|                  |                            |                   |                   |                |        |
|------------------|----------------------------|-------------------|-------------------|----------------|--------|
| <b>Reg. date</b> | 21/06/2016                 | <b>Colour</b>     | GREY              | <b>Gearbox</b> | MANUAL |
| <b>Year</b>      | 2016                       | <b>VIN</b>        | TMAJ3815LHJ207953 | <b>Gears</b>   | 6      |
| <b>Mileage</b>   | 115,000 Miles<br>Warranted | <b>Body Style</b> | Estate            |                |        |
| <b>Fuel Type</b> | Diesel                     | <b>MOT Due</b>    | 21/02/2027        |                |        |

£90 ADDITIONAL FEE

### Tyres

|              |
|--------------|
| <b>NSF</b>   |
| <b>NSR</b>   |
| <b>OSF</b>   |
| <b>OSR</b>   |
| <b>Spare</b> |