

#### 46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

## **VEHICLE INSPECTION REPORT**



## Kia Stonic 1.0T GDi 99 2 5dr DCT

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	Present		
Details					
Reg. date	21/09/2021	Service history	Yes	CAP Average	£10,900.00
Year	2021	Service documents	Service Book	CAP Below	£9,700.00
Mileage	26,252 Miles Warranted	Number of stamps	1	Gearbox	SEMI AUTO
		Last service date	29/11/2024	Gears	7
Fuel Type	Petrol	Last service miles	26,001	Doors	5
Colour	YELLOW	MOT Due	11/05/2026		
VIN	KNAD6817VN6591663	CAP Clean	£12,050.00		
Body Style	Hatchback				

#### Last service 29/11/2024 @ 26001 miles (1 MAIN DEALER SERVICE)

Tyres			
NSF	BUDGET	4.0mm	
NSR	MICHELIN	4.0mm	
OSF	BUDGET	3.0mm	
OSR	MICHELIN	4.0mm	
Spare			

### Features

#### Bluetooth connection

- Rear wiper
- Body coloured bumpers
- Front armrest Rear electric windows
- ABS
- Traction control
- Alloy wheels

- Cruise control
- Electric door mirrors Audio remote control Audio remote control ٠ ٠
- Front electric windows •
- Rear headrests ٠
- Drivers airbag ٠

٠

- Central locking
- PAS

  - Air conditioning
    Front head restraints
    Solid Paint
  - Isofix child seat anchor points

  - Remote central locking
- Rear parking sensorDigital radio
- Climate control ٠
- Height adjustable drivers seat
  3x3 point rear seat belts
- Passenger airbag
  Partial leather seat trim

### **Photos**






















## **Condition Check**



### **Damage Photos**



# No Image

1: Boot Lid Scratched Over 25mm Not Thru Paint 2: Qtr Panel osr Scratched Over 25mm Not Thru Paint



3: Door osf Dented Over 2 UpTo 10mm

4: Bonnet Dented Over 2 UpTo 10mm

# No Image

# No Image

5: Bumper Front Scratched Over 25mm Not Thru Paint 6: Door nsf Scratched Over 25mm Not Thru Paint

Interior

Carpet Condition	Average
Seat Condition	Average

**Upholstery Condition** Average Odour No

### Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs OK	Gearbox 1st and Reverse Test OK
Brakes OK	Clutch Slip Test from Static OK
Turbo Boosting OK	Gearbox Static Gear Selection (engine running) OK
Parking Brake OK	No Excessive Smoking OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	ОК		
Windows	OK	Radio	ОК
		Steering	OK