



VEHICLE INSPECTION REPORT

GY69KZO

Nissan Micra 1.0 IG-T 100 Acenta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	24/10/2019	Body Style	Hatchback	Last service miles	19,853
Year	2019	Keys	2	MOT Due	23/10/2026
Mileage	78,228 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLUE	Number of stamps	2	Doors	5
VIN	VNVK1400963970797	Last service date	22/10/2021		

£100 ADDITIONAL FEE

Last service 22/10/2021 at 19,853 miles- 2 main dealer services Service due message displayed

Tyres

NSF	SUNNY	3.0mm
NSR	CONTINENTAL	5.0mm
OSF	MICHELIN	5.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Up To 25mm Thru Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Dented
With Paint Damage



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osr
Dented
Between 10mm + 30mm



12: Door osr
Chipped
1 To 5



13: Door osf
Scratched
Over 25mm Thru Paint



14: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK