



VEHICLE INSPECTION REPORT

GY20UVD

Audi Q7 45 TDI Quattro S Line 5dr Tiptronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/07/2020	Body Style	Estate	Last service miles	60,556
Year	2020	Keys	2	MOT Due	25/07/2026
Mileage	63,605 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	SILVER	Number of stamps	3		
VIN	WAUZZZ4MXLD004209	Last service date	06/01/2026		

£90 ADDITIONAL FEE.

Last service 06/01/2026 at 60556 miles (3 main dealer services).

Tyres


NSF	GOODYEAR	6.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	6.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel Arch Extension ns
Scratched (Painted)
UpTo 25mm Thru Paint



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Bumper Reflector osr
Broken
Replace



10: Door osr
Dented
With Paint Damage




11: Door osf
Scratched
Over 25mm Thru Paint



12: Wing osf
Scratched
UpTo 25mm Thru Paint



13: Screen Front
Cracked
Replace



14: Roof
Chipped
Edge Chip



15: Qtr Panel nsr
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK