



VEHICLE INSPECTION REPORT

GJ16WLL

Seat Ibiza 1.8 TSI Cupra 3dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/03/2016	Body Style	Hatchback	Last service miles	61,449
Year	2016	Keys	2	MOT Due	30/07/2026
Mileage	78,575 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	9	Doors	3
VIN	VSSZZZ6JZGR095354	Last service date	23/07/2025		

£100 ADDITIONAL FEE

LAST SERVICE 23/07/2025 @ 61,449 MILES (9 SERVICES, 2 MAIN DEALER - BOOK & PRINT) Oil service messages displayed

Tyres

NSF	TRIANGLE	5.0mm
NSR	WESTLAKE	4.0mm
OSF	BUDGET	4.0mm
OSR	WESTLAKE	4.0mm

Spare

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Poor Previous Repair
Poor Paint



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Wheel nsr
Scratched
Up To 50mm



7: Qtr Panel nsr
Dented
Over 30mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Wheel osf
Scratched
Up To 50mm



10: Door osf
Chipped
Edge Chip



11: Wheel osf
Scratched
Over 50mm



12: Sill os
Scratched
Over 25mm Thru Paint



13: Wing osf
Chipped
1 To 5



14: Air Vents nsf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK