

VEHICLE INSPECTION REPORT

VA59KVG

Toyota IQ 1.0 VVT-i 2 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
 GRADE
5

Details

Reg. date	22/01/2010	Body Style	Hatchback	Last service miles	51,129
Year	2010	Keys	1	MOT Due	14/11/2026
Mileage	70,351 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Electronic / Online	Gears	5
Colour	SILVER	Number of stamps	4	Doors	3
VIN	JTNML11060J044880	Last service date	16/04/2018		

LAST SERVICE 16/4/18 @ 51,129 MILES (4 MAIN DEALER CONFIRMED BY CURRIE MOTORS KINGSTON & STONE ARCE TOYOTA DURHAM)

Tyres

NSF	CONTINENTAL	Damaged
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Rear wiper
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels
- Radio/CD
- Climate control
- ABS
- Central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Tyre nsf
Damaged
Replace



2: Wheel osf
Scratched
Over 50mm



3: Wing osf
Scratched
UpTo 25mm Thru Paint



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Screen Front
Chipped
Over 10mm



7: Wheel nsf
Scratched
Over 50mm



8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Over 30mm



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: Qtr Panel osr
Rusted
Over 5mm



16: Door osf
Scratched
Over 25mm Thru Paint



17: Door osf
Rusted
UpTo 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK