

VEHICLE INSPECTION REPORT

GX16FFT

Honda Civic 1.4 i-VTEC S 5dr

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	12/03/2016	Body Style	Hatchback	Last service miles	111,312
Year	2016	Keys	2	MOT Due	23/02/2027
Mileage	111,312 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	7	Doors	5
VIN	SHHFK1740FU005788	Last service date	15/06/2026		

Last service 15/06/2026 at 111,312 miles- 7 services (6 main dealer) Osr brake calliper leaking

Tyres

NSF	BUDGET	2.0mm
NSR	NEXEN	4.0mm
OSF	SUNNY	4.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osr
Chipped
1 To 5



3: Wheel osr
Corroded
Light



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Bumper Rear
Chipped
1 To 5



6: Wheel nsr
Corroded
Light



7: Door nsr
Chipped
1 To 5



8: Door nsf
Chipped
Edge Chip



9: Door nsf
Chipped
1 To 5



10: Wheel nsf
Corroded
Light



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Bonnet
Scratched
Over 25mm Thru Paint



13: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK