



VEHICLE INSPECTION REPORT

PX12ZWN

Mini Hatchback 1.6 Cooper 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	19/06/2012	Keys	2	CAP Average	£1,225.00
Year	2012	Service history	Yes	CAP Below	£825.00
Mileage	114,027 Miles Warranted	Number of stamps	9	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	09/10/2024	Gears	6
Colour	RED	Last service miles	110,962	Doors	3
VIN	WMWSU320X0T109833	MOT Due	13/08/2025		
Body Style	Hatchback	CAP Clean	£1,625.00		

Bonnet doesn't open

Tyres

NSF	BUDGET	3.0mm
NSR	RAPID	5.0mm
OSF	LAUFENN	5.0mm
OSR	RAPID	4.0mm
Spare		

Features


- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Door osf
Scratched
Over 25mm Not Thru Paint



3: Qtr Panel osr
Dented
With Paint Damage



4: Bumper Rear
Poor Previous Repair
Paint Flake




5: Tailgate
Chipped
Multiple Chips



6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




7: Wheel nsr
Scratched
Over 50mm



8: Door nsf
Chipped
Edge Chip



9: Door nsf
Chipped
1 To 5



10: Door nsf
Scratched
UpTo 25mm Not Thru Paint



11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Chipped
Multiple Chips



13: Bumper Front
Scratched
UpTo 25mm Thru Paint



14: Bonnet
Chipped
Multiple Chips



15: Roof
Chipped
1 To 5



16: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK