



VEHICLE INSPECTION REPORT

GV22FWT

MG Mg Hs EXCLUSIVE

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	28/06/2022	Body Style	Estate	Last service miles	26,897
Year	2022	Keys	2	MOT Due	24/04/2027
Mileage	34,982 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	2		
VIN	LSJA24U98NN076475	Last service date	20/08/2024		

£90 ADDITIONAL FEE

Last service 20/08/2024 at 26,897 miles- 2 main dealer services Electric seats do not work

Tyres

NSF	GT RADIAL	6.0mm
NSR	MICHELIN	5.0mm
OSF	GT RADIAL	6.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Cruise control
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Navigation system
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Front electric windows
- ABS
- Central locking
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear headrests
- Passenger airbag
- Leather seat trim
- Metallic Paint
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Dented
With Paint Damage



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Dented
With Paint Damage



12: Door osf
Chipped
Edge Chip



13: Wing osf
Scratched
Over 25mm Thru Paint



14: Wheel osf
Scratched
Over 50mm



15: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint

16: Handle Outer osf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		