



# VEHICLE INSPECTION REPORT

**ND66UTG**

## Nissan Juke 1.6 Tekna 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy



### Details

Reg. date	13/01/2017	Body Style	Hatchback	Last service miles	72,278
Year	2017	Keys	2	MOT Due	16/08/2026
Mileage	80,505 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLACK	Number of stamps	8	Doors	5
VIN	SJNFBAF15U7304456	Last service date	31/07/2025		

£90 ADDITIONAL FEE.

Last service 31/07/2025 at 72,278 miles- 8 services (7 main dealer)  
 COPY OF V5 Gearbox fault

### Tyres


NSF	LANVIGATOR	4.0mm
NSR	RAPID	5.0mm
OSF	LANVIGATOR	4.0mm
OSR	RAPID	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel of  
Corroded  
Light



2: Wing of  
Scratched  
Up To 25mm Thru Paint



3: Wing osf  
Chipped  
1 To 5



4: Wheel nsf  
Corroded  
Light



5: Wheel osf  
Corroded  
Light



6: Wheel osr  
Corroded  
Light



7: Door osf  
Dented  
With Paint Damage



8: Door osr  
Dented  
Over 30mm



9: Bumper Rear  
Poor Previous Repair  
Paint Flake



10: Bumper Front  
Scratched  
Over 100mm Thru Paint



11: Bonnet  
Chipped  
1 To 5



12: Screen Front  
Chipped  
Up To 10mm



13: A Post os  
Chipped  
1 To 5



14: Lamp nsr  
Broken  
Replace



15: Door nsr  
Chipped  
1 To 5



16: Door nsr  
Dented  
2 Or Less UpTo 10mm



17: Door nsf  
Chipped  
1 To 5



18: Lamp osr  
Broken  
Replace

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK