

VEHICLE INSPECTION REPORT

VF16FLW

Vauxhall Astra 1.0T 12V ecoFLEX SRi Nav 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/07/2016	Body Style	Hatchback	Last service miles	55,846
Year	2016	Keys	2	MOT Due	31/01/2027
Mileage	91,194 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	7	Doors	5
VIN	W0LBF6EA4GG155033	Last service date	17/01/2023		

Last Service - 17.01.2023 at 55846 miles (7 services)

Tyres


NSF	RAPID	4.0mm
NSR	TRIANGLE	4.0mm
OSF	ROADSTONE	3.0mm
OSR	CONTINENTAL	2.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Door osr
Chipped
Edge Chip



7: Qtr Panel osr
Dented
Between 10mm + 30mm



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Chipped
Edge Chip



12: Door nsf
Chipped
Edge Chip



13: Door nsf
Chipped
1 To 5



14: Wing nsf
Scratched
Over 25mm Thru Paint



15: Wheel nsf
Scratched
Over 50mm

16: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK