



# VEHICLE INSPECTION REPORT

**HN18NLF**

## VOLKSWAGEN POLO 1.0 TSI 95 SE 5dr

### Inspection

### Vehicle

VAT	Margin
V5	Present

### Details

<b>Reg. date</b>	29/06/2018	<b>Body Style</b>	Hatchback	<b>MOT Due</b>	22/07/2026
<b>Year</b>	2018	<b>Service history</b>	Yes	<b>Gearbox</b>	MANUAL
<b>Mileage</b>	41,000 Miles Warranted	<b>Service documents</b>	Service Book	<b>Gears</b>	5
<b>Fuel Type</b>	PETROL	<b>Number of stamps</b>	4	<b>Doors</b>	5
<b>Colour</b>	GREY	<b>Last service date</b>	25/06/2025		
<b>VIN</b>	WVWZZZAWZJU042959	<b>Last service miles</b>	33,518		

Last Service - 25.06.2025 at 33518 miles (4 services)

### Tyres

NSF
NSR
OSF
OSR
Spare